


14/1
28 K80

FIG. 1



09901000.070904

FIG. 2A





FIG. 2B



05504000.070904

09301000-070901

FIG. 3A





FIG. 3B



01-7-6: 9:20AM: 下田特許事務所

09401000.070901






FIG. 6




FIG. 7A




FIG. 7B




FIG. 7C






FIG. 7D



09301000.070901

FIG. 8



0335898558

05501000.070901




FIG. 10




FIG. 11




FIG. 12





FIG. 13







FIG. 15 A





FIG. 15 B



0335888558

FIG. 16






FIG. 17



0335888558

5



09901000.070901

FIG.19A
(PRIOR ART)




FIG.19B
(PRIOR ART)

